



Zele, April 2020

Subject: Updated material reference

Dear Brady Customer,

Brady wants to inform you that Brady material B-483 will have an updated material reference.

Due to a non-conformity with UL follow up testing, the maximum temperature rating for the metal surfaces needed to be lowered.

The material characteristics do not change. However, because of lowering the maximum temperature rating, UL requires a designation change from B-483 to B-483A. The TDS has been updated.

We are committed to a successful transition, while providing you the best possible products. Should you have any further questions, please contact your supplier of Brady materials.

Thank you for your understanding and continued support of Brady.

Sincerely yours,

David Verloes  
Sr Product Marketing Manager Materials  
Brady EMEA